

Shewhart Control Charts

I Chart: Formula



Data

Month	Expenditure (I)	MR
1	5814.23	
2	5885.34	71.11
3	5803.66	81.68
4	5935.03	131.37
5	5583.37	351.66
6	5456.08	127.28
7	5386.95	69.14
8	5907.34	520.39
9	5537.06	370.28
10	5837.90	300.84
11	4356.85	1481.05
12	5563.29	1206.45
13	5638.69	75.39
14	5399.15	239.54
15	5877.60	478.46
16	5952.15	74.54
17	5367.89	584.25
18	5677.77	309.88
19	5145.06	532.71
20	5633.67	488.61
Total ($\sum i$)	111759.07	
$\sum mr$	7494.64	

**Calculation**

$$\sum i = 111759.07 \\ k = 20$$

$$CL = \bar{i} = \frac{\sum i}{k}$$

$$\bar{i} = \frac{\sum i}{k} = \frac{111759.07}{20} = 5587.9535$$

$$\frac{\sum mr}{k-1} = mrbar \\ \frac{7494.64}{20-1} = 394.455 \text{ (to 3. d. p)}$$

* Remove any moving range bigger than the ULmr and recalculate the average moving range (mrbar), only do this process once.

$$ULmr = 3.27 * mrbar$$

$$ULmr = 3.27 * 394.455$$

$$ULmr = 1289.868 \text{ (to 3.d.p)}$$

* (Month 11: 1481.05 > ULmr)

$$\text{New mrbar} = \frac{\sum mr - 1481.05}{k-(1+\text{no. of values larger than ULmr})} = \frac{7494.64 - 1481.05}{20-(2)}$$

$$UCL = \bar{i} + (2.66 * \text{New mrbar})$$

$$= 5587.9535 + (2.66 * 334.088)$$

$$= 5587.9535 + (888.67408)$$

$$= 6476.62758 \text{ (6476.63 to 2.d.p)}$$

$$LCL = \bar{i} - (2.66 * \text{New mrbar})$$

$$= 5587.9535 - (2.66 * 334.088)$$

$$= 5587.9535 - (888.67408)$$

$$= 4699.27942 \text{ (4699.28 to 2.d.p)}$$

$$CL = 5587.95 \text{ (to 2.d.p)}$$

Plot the expenditure, CL, UCL and LCL as seen on the chart

Legend + Chart

I = expenditure per sub group (per row)

mr = difference between consecutive points (moving ranges)

ULmr = upper limit moving range

$\sum i$ = sum of incidents

$\sum mr$ = sum of moving ranges

k = number of sub groups

CL = center line (Mean)

UCL = upper control limit ($\bar{i} + (2.66 * mrbar)$)

LCL = lower control limit ($\bar{i} - (2.66 * mrbar)$)

I Chart